

Existing Conditions at 215 Locust Street (formerly 260 West Riverside Drive)

The following photographs show existing vehicle driveways, pedestrian walkways, parking, drainage/stormwater features, landscaped areas, trash enclosure, and fencing.



FIGURE 1 View of Main Driveway Approach off Locus Street (Image date: August 16, 2021)



FIGURE 2 View of School's Front Entry from Main Driveway (Image date: August 16, 2021)



FIGURE 3 View of Bio-retention Swale from Main Driveway (Image date: August 16, 2021)





FIGURE 4 Views of Bio-retention Swale (Image date: August 16, 2021)



FIGURE 5 View of Trash Enclosure (Image date: August 16, 2021)



FIGURE 6 View of Driveway Approach off West Riverside Drive (Image date: August 16, 2021)



FIGURE 7 View of Driveway and Parking Lot off Riverside Drive (Image date: August 16, 2021)